


NOTE:

A) REMOVE STAINLESS STEEL SLEEVE AND REPLACE WITH 250-034131 & 250-035019 (KEEPING HOLES ALIGNED) USING HIGH TEMP RVT SILICONE.

B) APPLY WITH A LIBRAL AMOUNT OF BONDING AGENT (GREEN LOCK TIGHT)

C) APPLY STAINLESS STEEL BUSHING (CHAMFER TO THE OUTSIDE) OVER THE STAINLESS STEEL SLEEVE WITH BONDING AGENT

D) LUBE SPORTS NEEDLE WITH AXLE GREASE WAIT 24HR TO PRESSURIZE INFLATE DIAPHRAGM TO 5-10PSI (SPORTS NEEDLE TO BE INCLUDED W/TLR DOCUMENT WHEN FINISHED)



★ INDICATES CHANGE ON EFFECTIVE DATE

DESCRIPTION:
AXLE TRSN NB 3700# 70.25"FC
AIR TIGHT

PART #:
300-034277



EFFECTIVE DATE:
04-13-15

ECN:
897