


NOTE:

- A) REMOVE STAINLESS STEEL SLEEVE AND REPLACE WITH 250-034130 & 250-035020 (KEEPING HOLES ALIGNED) USING HIGH TEMP RVT SILICONE.
- B) APPLY WITH A LIBRAL AMOUNT OF BONDING AGENT (GREEN LOCK TIGHT)
- C) APPLY STAINLESS STEEL BUSHING (CHAMFER TO THE OUTSIDE) OVER THE STAINLESS STEEL SLEEVE WITH BONDING AGENT
- D) LUBE SPORTS NEEDLE WITH AXLE GREASE WAIT 24HR TO PRESSURIZE INFLATE DIAPHRAGM TO 5-10PSI (SPORTS NEEDLE TO BE INCLUDED W/TRLR DOCUMENT WHEN FINISHED)



DESCRIPTION:
AXLE TRSN NB 5500# 73.75"FC
AIR TIGHT

PART #:
300-034733



EFFECTIVE DATE:
04-13-15

ECN:
897